


ENGINE DELTA PRESSURE SENSOR FAILURES


INVENTORS: YUE YUN WANG, ET AL. ATTY. DOCKET NO.: 29766-71516

PAGE 2 OF 7



ENGINE DELTA PRESSURE SENSOR FAILURES INVENTORS: YUE YUN WANG, ET AL. ATTY. DOCKET NO.: 29766-71516

PAGE 3 OF 7







FIG. 4

. 0

ENGINE DELTA PRESSURE SENSOR FAILURES INVENTORS: YUE YUN WANG, ET AL.

ATTY. DOCKET NO.: 29766-71516

PAGE 4 OF 7



 ΔP 122 S -120 ES_I 126 -116 -132 -130 **SSFC** E AND 134/ ۷P -136 138 EGRP₁ 142 -140 DIAGNOSTIC ENABLE LOGIC

FIG. 6

ENGINE DELTA PRESSURE SENSOR FAILURES

INVENTORS: YUE YUN WANG, ET AL. ATTY. DOCKET NO.: 29766-71516

PAGE 5 OF 7




FIG. 8

ENGINE DELTA PRESSURE SENSOR FAILURES INVENTORS: YUE YUN WANG, ET AL. ATTY. DOCKET NO.: 29766-71516

PAGE 6 OF 7




FIG. 9





FIG. 10

ENGINE DELTA PRESSURE SENSOR FAILURES INVENTORS: YUE YUN WANG, ET AL.

ATTY. DOCKET NO.: 29766-71516

PAGE 7 OF 7






FIG. 12